

John Kellard, P.E. David Sessions, RLA, AICP Joseph M. Cermele, P.E., CFM Jan K. Johannessen, AICP

RECEIVED

PLANNING DEPARTMENT

AUG 1 2 2021

TOWN OF YORKTOWN

August 12, 2021

Planning Board Town of Yorktown 1974 Commerce Street, Room 222 Yorktown Heights, New York 10598

Attn:

Mr. John A. Tegeder, R.A.

Director Planning

RE:

Public Informational Hearing Response

Parking Lot Expansion GHP Strang, LLC

2649-2651 Strang Blvd

Dear Mr. Tedeger:

On behalf of our client, GHP Strang, LLC, please accept this letter as a follow up to conversations had with the Planning Board during the Public Informational Hearing of August 9, 2021 for the above-referenced project. The purpose of this letter is to provide clarification to the Planning Board related to comments provided by a noticed neighbor expressing concerns and questions related to the project, as it relates to the proposed parking lot, temporary access road, soil stockpiling, and existing or proposed vegetation, as well as to clarify ongoing activities at the site.

Please note that various construction aspects associated with the overall building renovations and existing utilities are underway and are all being performed with current, valid permits as required by the Town. While this office is not directly involved with the current building renovations, at the request of the Planning Board, we have performed a site inspection and prepared the enclosed Construction Inspection Report, dated August 11, 2021, for your information. The report identifies current activities taking place at the site and provides our professional opinion with regard to erosion and sediment controls.

The noticed neighbor questioned the need for the proposed parking lot expansion. As was explained to the Board, the owner has experienced difficulty in recent years in finding tenants to occupy the lower level of the northernmost portion of the building. As expressed by potential tenants, this is largely due to the limited available parking in this area of the site and the lack of ADA accessible access to the lower level. Aside from the approximately 60 parking spaces provided at the north end of the site, tenants utilizing this space would be required to park on the south end of the site and walk approximately 600 feet to gain access to the lower level of the building. The project proposes a lower parking area, including 25 parking spaces and a loading dock. The loading dock has been designed to accommodate vans and typical delivery

CIVIL ENGINEERING | LANDSCAPE ARCHITECTURE | SITE & ENVIRONMENTAL PLANNING

Mr. John A. Tegeder, R.A. August 12, 2021 Page 2 of 3

trucks (i.e., FEDEX and UPS). In addition, the plan proposes two (2) ADA compliant access ramps; one at the existing upper-level entry and a second at the proposed lower parking lot.

With regard to the "road" referenced by the noticed neighbor, please note that this is a temporary construction access road and is required to provide adequate access for the lower-level building demolition and renovations. A temporary construction access road has been constructed, connecting the existing upper parking lot to the lower level. The temporary access road is stable, and all downgradient areas are protected by temporary silt fence which is in good working order. No erosion was noted at the time of our inspection, nor were any corrective actions required.

With regard to concerns for soil stockpiles, please note that the material in question is directly related to the removal of an existing 20,000 gallon underground fuel-oil storage tank. The tank removal and environmental remediation is being conducted by a Licensed Contractor under current permits from the Town. At the time of our inspection, excavated material was being stockpiled within the existing paved parking lot and is covered daily with plastic tarps to prevent erosion. The parking lot is swept daily at the end of the contractor's workday. Upon removal of the underground storage tank the clean fill is to be used for backfill material in the excavated area and any disturbed areas will be stabilized with topsoil and seed. No erosion was noted at the time of our inspection nor were any corrective actions required.

Finally with regard to existing vegetation, as was noted by the neighboring property owner, the existing wooded area to the north is located within properties owned by the adjacent neighbors and not controlled by my client. No improvements or activities are proposed within these areas. The wooded area, as was noted during our presentation to the Planning Board, consists largely of deciduous trees. The property owner agreed and added that much of the wooded area on his property has been overtaken by vines. In an effort to mitigate any potential visual impact from the project resulting from the proposed short retaining wall and the potential for any off-site light-shed from vehicle headlights, as shown on the current site plan, our client proposes to plant an evergreen screening buffer along the full length of the proposed driveway that shares the common property line between the project site and the adjacent property owners. It is proposed to plant Green Giant Arborvitae with a planting height of six (6) to eight (8) feet. As was discussed at the Public Informational Hearing, the selected species are appropriate for this area due to the limited space on site for the plantings and the rapid growth for nearly immediate screening.

We would like to request that the Planning Board conduct a site visit at their convenience to witness the current activities and get a better understanding of the project, as proposed. We will make ourselves available at a time that is convenient for the Planning Board. We also request that the Planning Board consider scheduling a public hearing for this matter for your September 13 Planning Board Agenda.

Mr. John A. Tegeder, R.A. August 12, 2021 Page 3 of 3

We trust the above clarification and attached inspection report satisfy any concerns or questions the Planning Board and adjacent property owners may have expressed. We look forward to discussing this matter further with the Board. Should you have any questions or require any additional information please do not hesitate to contact me.

Very truly yours,

Joseph M. Cermele, P.E., CFM Kellard Sessions Consulting

Joseph M. Cermele

JMC/dc

cc: Michael Cinicolo

 $Https://kellardsessions consult i.s hare point.com/sites/Kellard/Project Docs P/YRGHP600/KSC Correspondence/2021-08-12_YRGHP600_Tegeder_PB Followup_Ltr.docx P/YRGHP600/KSC Correspondence/2021-08-12_YRGHP600_Tegeder_PB Followup_Ltr.docx P/YRGHP600/KSC Correspondence/2021-08-12_YRGHP600/KSC Correspondence/2021-08-12_YRGH$

CONSTRUCTION INSPECTION REPORT	
Date: 08-11-2021 Day: S M T V W Th F S Property Owner: GHP Strang LLC, Mike Cinicolo Property Address: 2649-2651 Strang Blvd Property SBL: Email: mcinicolo@ghpoffice.com Contractor: Innovative Environmental Services Inc Phone: 914-449-6608 Email:	Permit #:
The state of the s	
At the request of the Planning Board, as discussed at the 8/9/21 Public Informational Hearing, this office conducted an inspection of recent site activities related to excavation and soil stockpiling. At the time of the inspection, the contractor was excavating and exposing the existing 20,000 gal underground storage tank (fuel oil) proposed to be removed. It was reported by the owner that the removal is being conducted under a current Building Permit. In addition, demolition activities were taking place within the lower level of the existing building, also in accordance with current Building Permits. A temporary construction access road had been constructed.	
COMMENTS / REMARKS - Excavated material associated with the ongoing tank removal is being separated and temporarily stockpiled in the existing parking lot. The clean soil stockpile is covered with plastic tarps daily to prevent erosion. The contaminated soil stockpile is placed on two layers of poly-liner and then covered with plastic tarps daily to prevent erosion. The contaminated soil will be removed and disposed off site. The clean soil will be used to backfill the excavation once the tank is removed. - The internal building demolition activities continue at the lower level. The downgrade area of the temporary access road is protected by silt fence. - No erosion was observed at the time of the inspection and all controls appeared to be installed correctly. - The contractor is sweeping the parking lot daily to prevent off-site sediment transport. - No corrective actions were required at the time of the inspection.	
Joseph M. Cermele, PE Inspector (print name)	In pector (signature)
RECEIVED PLANNING DEPARTMENT	KELLARI

Page 1 of 1

AUG 1 2 2021






Photo 1 – Cut Material Stockpiles



Photo 2 – Cut Material Stockpile – Clean Fill





Photo 3 - Contaminated Soil Stockpile



Photo 4 - Oil Tank Removal





Photo 5 – 20,000 gal UST




Photo 6 – Lower Level Demo





Photo 7 - Lower Level Demo and Temporary Construction Access Road



Photo 8 – Temporary Construction Access Road





Photo 9 - Temporary Construction Access Road

